

## Recommended Starting Feeds [IPT]

Light	General	Heavy
Machining	Purpose	Machining

## At .320 Axial Depth of Cut (ap)

Insert	Recommended Starting Feed per Tooth (Fz) in Insert Relation to % of Radial Engagement (ae)															Insert
Geometry		5% 10%					20%			30%			4	<del>40–100</del> %	Geometry	
.ELDJ	.005	.017	.031	.004	.013	.023	.003	.009	.017	.002	.008	.015	.002	.008	.014	.ELDJ
.ELD	.005	.017	.031	.004	.013	.023	.003	.009	.017	.002	.008	.015	.002	.008	.014	.ELD
.SGD	.009	.020	.035	.007	.014	.025	.005	.011	.019	.004	.009	.016	.004	.009	.015	.SGD
.SHD	.009	.023	.037	.007	.017	.027	.005	.013	.020	.004	.011	.017	.004	.010	.016	.SHD

## At .100 Axial Depth of Cut (ap)

Insert	Recommended Starting Feed per Tooth (Fz) in Relation to % of Radial Engagement (ae)															Insert
Geometry	5%			10%			20%			30%			4	40-100%	Geometry	
.ELDJ	.007	.024	.043	.005	.017	.031	.004	.013	.023	.003	.011	.020	.003	.010	.018	.ELDJ
.ELD	.007	.024	.043	.005	.017	.031	.004	.013	.023	.003	.011	.020	.003	.010	.018	.ELD
.SGD	.013	.027	.048	.009	.019	.034	.007	.015	.026	.006	.013	.022	.005	.012	.020	.SGD
.SHD	.013	.032	.051	.009	.023	.037	.007	.017	.027	.006	.015	.024	.005	.014	.022	.SHD

# At .060 Axial Depth of Cut (ap)

Insert	Recommended Starting Feed per Tooth (Fz) in Relation to % of Radial Engagement (ae)															Insert
Geometry		5%			10%		20%			30%				40-100%	Geometry	
.ELDJ	.008	.030	.054	.006	.021	.039	.005	.016	.029	.004	.014	.025	.004	.013	.023	.ELDJ
.ELD	.008	.030	.054	.006	.021	.039	.005	.016	.029	.004	.014	.025	.004	.013	.023	.ELD
.SGD	.016	.034	.060	.011	.024	.043	.009	.018	.032	.007	.016	.028	.007	.014	.025	.SGD
.SHD	.016	.040	.064	.011	.029	.046	.009	.021	.034	.007	.019	.030	.007	.017	.027	.SHD

## At .040 Axial Depth of Cut (ap)

Insert	Recommended Starting Feed per Tooth (Fz) in Relation to % of Radial Engagement (ae)															Insert
Geometry		5%			10%			20%			30%			40–100%	Geometry	
.ELDJ	.010	.036	.066	.007	.026	.047	.005	.019	.035	.005	.017	.030	.004	.015	.028	.ELDJ
.ELD	.010	.036	.066	.007	.026	.047	.005	.019	.035	.005	.017	.030	.004	.015	.028	.ELD
.SGD	.019	.041	.073	.014	.029	.052	.010	.022	.039	.009	.019	.034	.008	.017	.031	.SGD
.SHD	.019	.048	.078	.014	.034	.056	.010	.026	.041	.009	.022	.036	.008	.021	.033	.SHD

NOTE: Use "Light Machining" values as starting feed rate.
Please see pages X22–X37 for recommended starting speeds.



