

■ Recommended Starting Speeds [SFM]

Material Group		KYHS10			KYSM10			KYSP30			KYS30		
P	1	—	—	—	—	—	—	—	—	—	—	—	—
	2	—	—	—	—	—	—	—	—	—	—	—	—
	3	—	—	—	—	—	—	—	—	—	—	—	—
	4	—	—	—	—	—	—	—	—	—	—	—	—
	5	—	—	—	3960	3200	2380	3000	2400	1800	—	—	—
	6	—	—	—	3960	3200	2380	3000	2400	1800	—	—	—
M	1	—	—	—	3960	3200	2380	—	—	—	—	—	—
	2	—	—	—	3740	3000	—	—	—	—	—	—	—
	3	—	—	—	2760	2400	—	—	—	—	—	—	—
K	1	—	—	—	—	—	—	—	—	—	—	—	—
	2	—	—	—	—	—	—	—	—	—	—	—	—
	3	—	—	—	—	—	—	—	—	—	—	—	—
N	1-2	—	—	—	—	—	—	—	—	—	—	—	—
	3	—	—	—	—	—	—	—	—	—	—	—	—
S	1	1680	1320	960	3490	2860	2220	2640	2160	1680	2640	2160	1680
	2	1680	1320	960	3490	2860	2220	2640	2160	1680	2640	2160	1680
	3	2400	2040	1680	5080	4130	3180	3840	3120	2400	3840	3120	2400
	4	—	—	—	—	—	—	—	—	—	—	—	—
H	1	1200	1020	780	—	—	—	—	—	—	—	—	—

NOTE: FIRST choice starting speeds are in **bold** type.
As the average chip thickness increases, the speed should be decreased.

■ Recommended Starting Feeds [IPT] • RPGN06..

Light Machining	General Purpose	Heavy Machining
-----------------	-----------------	-----------------

At .125 Axial Depth of Cut (ap)

Insert Geometry	Programmed Feed per Tooth (fz) as a % of Radial Depth of Cut (ae)														Insert Geometry
	10%			20%			30%			40%			50-100%		
..E	.005	.005	.006	.004	.004	.004	.003	.003	.004	.003	.003	.003	.003	.003	..E

At .063 Axial Depth of Cut (ap)

Insert Geometry	Programmed Feed per Tooth (fz) as a % of Radial Depth of Cut (ae)															Insert Geometry
	10%			20%			30%			40%			50-100%			
..E	.005	.006	.007	.004	.004	.005	.004	.004	.004	.003	.004	.004	.003	.004	.004	..E

At .031 Axial Depth of Cut (ap)

Insert Geometry	Programmed Feed per Tooth (fz) as a % of Radial Depth of Cut (ae)															Insert Geometry
	10%			20%			30%			40%			50-100%			
..E	.007	.008	.009	.005	.006	.006	.005	.005	.006	.004	.005	.005	.004	.005	.005	..E

At .016 Axial Depth of Cut (ap)

Insert Geometry	Programmed Feed per Tooth (fz) as a % of Radial Depth of Cut (ae)															Insert Geometry
	10%			20%			30%			40%			50-100%			
..E	.010	.011	.012	.007	.008	.009	.006	.007	.008	.006	.007	.007	.006	.006	.007	..E

NOTE: Use "Light Machining" values as starting feed rate.

Copy Mills