


1 No. of teeth	0° Helix
-------------------	-------------



Note: • As cutting edge is very sharp, please handle carefully.

- Please keep the overhang length from milling chuck of tool as short as possible.
- Please use the endmill on a machine with sufficient rigidity.

Cat. No.	Stock	Dimensions (mm)				
	DX140	$\phi D_c$	$\phi D_s$	$\ell$	$\ell_s$	$L$
DEB1040	○	4.0	6.0	3.5	32	45
DEB1050	○	5.0			35	50
DEB1060	○	6.0	8.0	5	37	55
DEB1070	○	7.0			40	60
DEB1080	○	8.0	10.0	5	45	65
DEB1090	○	9.0				
DEB1100	○	10.0	12.0	5	45	65
DEB1110	○	11.0				
DEB1120	○	12.0				

### Standard cutting conditions

#### DEB1000

For side milling  $a_p \geq 3D$ ,  $a_e = .004$  in

Work materials	Aluminum alloys, Copper alloys	
Speed $v_c$ (SFM)	400 ~ 590	
Condition Mill dia. (mm)	No. of revolutions $n$ (min <sup>-1</sup> )	Table feed $V_f$ (in/min)
	$\phi 4$	12,000
$\phi 5$	9,600	5
$\phi 6$	8,000	
$\phi 8$	6,000	
$\phi 10$	4,800	
$\phi 12$	4,000	4

- Set the protrusion length as short as possible. Reduce number of revolutions and table feed in order to prevent chattering when the protrusion length is long.
- Use the machine with high rigidity.
- Adjust the number of revolutions and the table feed according to the situation of use (depth of cut or machine rigidity etc.).