



RECOMMENDED CUTTING CONDITIONS

Work material		Carbon steel, Cast iron, Alloy steel (–30HRC) AISI 1050, AISI No 35 B, AISI P20				Alloy steel, Tool steel, Pre-hardened steel AISI H13, AISI W1-10, AISI P21			
Dia. DC (mm)	Comer radius RE (mm)	Revolution (min ⁻¹)	Feed rate (mm/min)	Depth of cut ap (mm)	Depth of cut ae (mm)	Revolution (min ⁻¹)	Feed rate (mm/min)	Depth of cut ap (mm)	Depth of cut ae (mm)
2	R 0.5	33000	10000	0.08	0.8	27000	8400	0.05	0.8
3	R 0.75	22000	11000	0.12	1.2	18000	9000	0.08	1.2
4	R 1	17000	12000	0.15	1.5	14000	9500	0.12	1.5
5	R 1.2	13000	13000	0.20	2.0	11000	11000	0.15	2.0
6	R 1.5	11000	13000	0.25	2.5	9000	11000	0.15	2.5
7	R 1.5	9400	13000	0.25	3.0	7800	11000	0.15	3.0
8	R 2	8200	13000	0.30	3.0	7000	11000	0.20	3.0
9	R 2	7300	13000	0.30	4.0	6000	11000	0.20	4.0
10	R 2	6500	13000	0.30	4.5	5500	11000	0.20	4.5
11	R 2	6000	12000	0.30	5.5	5000	10000	0.20	5.5
12	R 3	5500	12000	0.45	4.5	4600	10000	0.30	4.5
13	R 3	5000	12000	0.45	5.5	4200	10000	0.30	5.5
16	R 3	4100	10000	0.45	7.5	3400	8800	0.30	7.5

Depth of cut 

Work material		Hardened steel (45–55HRC) AISI H13				Hardened steel (55–62HRC) AISI D2			
Dia. DC (mm)	Comer radius RE (mm)	Revolution (min ⁻¹)	Feed rate (mm/min)	Depth of cut ap (mm)	Depth of cut ae (mm)	Revolution (min ⁻¹)	Feed rate (mm/min)	Depth of cut ap (mm)	Depth of cut ae (mm)
2	R 0.5	24000	7500	0.04	0.8	16000	3000	0.03	0.8
3	R 0.75	16000	8500	0.06	1.2	11000	3300	0.05	1.2
4	R 1	12000	8800	0.08	1.5	8000	3500	0.07	1.5
5	R 1.2	9600	9500	0.10	2.0	6400	3800	0.08	2.0
6	R 1.5	8000	9600	0.10	2.5	5300	3800	0.10	2.5
7	R 1.5	6900	9600	0.10	3.0	4600	3800	0.10	3.0
8	R 2	6000	9600	0.15	3.0	4000	3800	0.13	3.0
9	R 2	5300	9500	0.15	4.0	3800	3800	0.13	4.0
10	R 2	4800	9500	0.15	4.5	3200	3800	0.13	4.5
11	R 2	4500	9000	0.15	5.5	2900	3500	0.13	5.5
12	R 3	4100	9000	0.25	4.5	2700	3500	0.20	4.5
13	R 3	3700	8900	0.25	5.5	2500	3500	0.20	5.5
16	R 3	3000	7800	0.25	7.5	2000	3200	0.20	7.5

Depth of cut 

Coefficients respective of tool overhang

Type	Overhang	Revolution	Feed rate	Depth of cut ap
Straight	L/D ≤ 5	100%	100%	100%
	L/D = 6	90%	80%	80%
	L/D = 7	80%	70%	70%
Taper neck	L/D = 6	100%	100%	100%
	L/D = 8	90%	80%	80%
	L/D ≥ 10	80%	70%	70%

- 1) The above table shows cutting conditions when machining with the corner radius cutting edge.
- 2) This table shows the cutting conditions with less than 5D overhang length. In the case of longer overhangs, the revolution and the feed rate should be reduced proportionately.
- 3) If the depth of cut is shallow, the revolution and feed rate can be increased.
- 4) Air blow or oil mist is recommended for good chip evacuation.
- 5) For profile machining such as moulds, machining conditions may differ considerably depending on the workpiece geometry, machining methods and depth of cut. Reduce the feed rate especially when machining the corner sections of a workpiece.
- 6) When machining inclinations in the Z direction, set the inclination angle at 2° and reduce the feed rate by 50%.
- 7) If the rigidity of the machine or the work materials installation is very low, or chattering and noise are generated, reduce the revolution and feed rate proportionately.