

Epoch Deep Ball Evolution

エポックディープボールエボリューション

標準切削条件表 Recommended cutting conditions EPDBE-PN EPDBE-ATH

高能率切削条件
High efficiency cutting condition

高精度切削条件
High accuracy cutting condition

高精度切削条件はA75ページを参照してください。
Please refer to P.A75 about high accuracy cutting conditions

推奨領域 Recommended range				PNシリーズ PN series											
				ATHシリーズ ATH series											
被削材 Work material				1	2	3	4	5	6						
				銅 Copper	炭素鋼・合金鋼 Carbon Steels, Alloy Steels (180~250HB)	ステンレス鋼・工具鋼 Stainless Steels, Tool Steels (25~35HRC)	プリハードン鋼 Pre-hardened Steels (35~45HRC)	焼入れ鋼 Hardened Steels (45~55HRC)	焼入れ鋼 Hardened Steels (55~65HRC)						
切込み比率 Ratio to standard depth of cut				120%		100%		90%		80%		65%		60%	
ボール半径R Ball Radius (mm)	外径 Tool Dia. (mm)	首下長 Under neck Length (mm)	ap (mm)	回転数 n min ⁻¹		送り速度 vf mm/min		回転数 n min ⁻¹		送り速度 vf mm/min		回転数 n min ⁻¹		送り速度 vf mm/min	
				1		2		6		10		15		20	
1.25		2.5		6		10		15		20		25		30	
1.5		3		8		10		13		16		20		25	
1.75		3.5		15		25		35		45					
2		4		10		13		16		20		25		30	
2.5		5		20		25		30		40					
3		6		12		20		30		40		50			

※(1) apは被削材グループ2での目安を示しています。その他のグループの場合は、上表の切込み比率を目安に調整してください。
 ※(2) リブ加工や止まり溝など、切りくずがつまりやすい切削の場合、切込み設定は基本切込みに切込み比率をかけて算出した切込み量を、さらにその80%まで小さくして使用してください。
 ※(3) aeの設定はap×切込み比率×3~5倍を目安に調整してください。仕上げ加工を行う場合、理論カスプハイトを計算し設定してください。

※(1) ap is shown as the criteria for Group 2 workpieces. For other groups, adjust the cutting depth according to the cutting depth factors in the above table.
 ※(2) When performing cutting where cutting chips may cause clogging, such as for rib cutting, blind grooves, etc., cutting depth setting should be set by multiplying a cutting depth factor to calculate the cutting depth amount, and this amount should then be reduced to 80% of the calculated value.
 ※(3) Adjust by setting ae to (3 to 5) × (ap × (cutting depth ratio)). When performing finishing processing, calculate the theoretical cusp height and set accordingly.

【切込み設定例】 EPDBE2020-10-ATHの工具で焼入れ鋼(50HRC)をリブ溝等高線切削する場合、切込み=0.21 (ap) × 0.65 (焼入れ鋼グループ5の切込み比率) × 0.8 (閉鎖域の切削) = 0.11 mm

Cutting depth setting example: When cutting rib groove contours in hardened steel (50HRC) using an EPDBE2020-10-ATH tool:
 Cutting depth = 0.21 (ap) × 0.65 (cutting depth factor for Group 5 hardened steel) × 0.8 (for closed-area cutting) = 0.11 mm

- 【注意】**
- ① PNコーティングはその性質上、通電性が微小です。従って、通電方式の工具長測定装置をご使用の際にはご注意ください。
 - ② 被削材、加工形状に合わせて、適切なクーラントを使用してください。
 - ③ この標準切削条件表は切削条件の目安を示すものです。実際の加工では加工形状、目的、使用機械等により条件を調整してください。
 - ④ 機械の回転数が足りない場合は、回転数と送り速度を同じ比率で下げてください。

【Note】

- ① PN coating is less electrically conductive. Therefore, electric transmitted measuring systems may not work.
- ② Use the appropriate coolant for the work material and machining shape.
- ③ These Recommended Cutting Conditions indicate only the rule of a thumb for the cutting conditions. In actual machining, the condition should be adjusted according to the machining shape, purpose and the machine type.
- ④ If the rpm of the machine is low, lower the feed rate also to put the rpm and feed rate in the same ratio.

