



Uncoated



AlTiN Coated



### Carbide Quick Change Boring Bars

Minimum Bore	Max. Depth	Quick Change Shank $\phi$	Uncoated Part #	AlTiN Coated Part #
.160	.200	3/16	<a href="#">RQB421140</a>	<a href="#">RQB421140A</a>
	.300	3/16	<a href="#">RQB421145</a>	<a href="#">RQB421145A</a>
	.400	3/16	<a href="#">RQB421150</a>	<a href="#">RQB421150A</a>
	.500	3/16	<a href="#">RQB421155</a>	<a href="#">RQB421155A</a>
	.600	3/16	<a href="#">RQB421160</a>	<a href="#">RQB421160A</a>
	.700	3/16	<a href="#">RQB421165</a>	<a href="#">RQB421165A</a>
	.800	3/16	<a href="#">RQB421170</a>	<a href="#">RQB421170A</a>
	.900	3/16	<a href="#">RQB421175</a>	<a href="#">RQB421175A</a>
	1.000	3/16	<a href="#">RQB421180</a>	<a href="#">RQB421180A</a>
	1.100	3/16	<a href="#">RQB421185</a>	<a href="#">RQB421185A</a>
.180	.200	3/16	<a href="#">RQB421190</a>	<a href="#">RQB421190A</a>
	.300	3/16	<a href="#">RQB421195</a>	<a href="#">RQB421195A</a>
	.400	3/16	<a href="#">RQB421200</a>	<a href="#">RQB421200A</a>
	.500	3/16	<a href="#">RQB421205</a>	<a href="#">RQB421205A</a>
	.600	3/16	<a href="#">RQB421210</a>	<a href="#">RQB421210A</a>
	.700	3/16	<a href="#">RQB421215</a>	<a href="#">RQB421215A</a>
	.800	3/16	<a href="#">RQB421220</a>	<a href="#">RQB421220A</a>
	.900	3/16	<a href="#">RQB421225</a>	<a href="#">RQB421225A</a>
	1.000	3/16	<a href="#">RQB421230</a>	<a href="#">RQB421230A</a>
	1.100	3/16	<a href="#">RQB421235</a>	<a href="#">RQB421235A</a>

Must be used with quick change bar toolholders on [page 499](#).

